



## INTRODUCTION

### **Numerical control :( NC)**


It can be defined as form of programmable automation in which the process is controlled by numbers, letters and symbols in NC the numbers forms a program of instructions designed for a particular work part or job.

When the job changes the program of instruction is changed. This capability will change program for each new job is what gives NC flexibility.

Ex: G00 X0 Y0 Z0

### **Computer numerical control :( CNC)**

Numerical control integrated computer control includes one or more microprocessor, mini computers. The logic function or program the control comprises a program that is stored in the memory.



### **Direct numerical control: (DNC)**

It can be defined as a manufacturing system in which a number of machines are controlled by a computer through direct connection & in real time.

Dept. of ME,

**NC motion control system:**


In NC there are 3 basic types of machine control system

1. Point to Point
2. Straight cut
3. Contouring

**1) Point to point**

It is also sometimes called positioning system. In point to point the objective of the machine tool control system is to the cutting to pre defined location once the tool reaches the defined location the machining operation is performed at that position.

EX: NC drill presses.




**2) Straight cut NC**

Straight cut control system is capable of moving the cutting tool, parallel to one of the major axes at controlled rate suitable for machining. It is therefore appropriate for performing milling operation to fabricate work piece of rectangular configurations.

# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

Dept. of ME,



## FUNDAMENTALS OF PART PROGRAMMING

### NUMERICAL CONTROL PROCEDURE

The following are the basic steps in NC procedure

- Σ Process Planning
- Σ Part Programming
- Σ Part Program entry
- Σ Proving the part program
- Σ Production

#### A) PROCESS PLANNING

The part programmer will often carry out the task of process planning. Process planning is the procedure of deciding what operations are to be done on the component, in what order, and with what tooling and work holding facilities. Both the process planning and part programming aspects of manufacture occur after the detail drawings of a component have

**ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER**  
been prepared. The following procedure may be used as a guide to assist the programmer, by  
describing each step required in preparing the method of production.

---

Dept. of ME,





## ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

- ∑ Determine planned stops for checking dimensional sizes where required by operator
  
- ∑ Determine cutting speeds based on
  - Component material, method of driving, rigidity of component
  - Tooling selected for roughing and finishing
  
- ∑ Determine the depths of cut and feeds for roughing operations
  
- ∑ Determine surface finish requirements, the cutter nose radius most suited for finishing operations and determine feed rates.
  
- ∑ Allocates tool offsets as required
  
- ∑ Complete planning sheet

### B) PART PROGRAMMING

- ∑ After completing the planning sheet, draw the component showing the cutter

|  |
|--|
|  |
|  |
|  |
|  |
|  |

- ∑ Indicate the ordering code for each tool and grade and type of inserts to be used.
  
- ∑ Write the part program according to the sequence of operations.


### C) PART PROGRAM ENTRY (OR) TAPE PREPARATION

The part program is prepared / punched on a 25 mm wide paper tape with 8 tracks and is fed to MCU in order to produce a component of interest on machine tool. Other forms of input media include, punched cards, magnetic tape, 35 mm motion picture film. The input to the NC system can be in two ways:

1. Manual data input
2. Direct Numerical control.

1) **Direct Data Input (MDI):** Complete part programs are entered into CNC control unit via the console keyboard. It is suited only for relatively simple jobs. The most common application for MDI is the editing of part programs already resident in controllers memory.

One variation of MDI is a concept called "Conversational Programming". CNC machines are programmed via a question and answer technique whereby a resident software program asks the operator a series of questions. In response to the operators input, and by accessing a pre-programmed data file, the computer control can.




- Select numerical values for use within machining calculations
- Perform calculations to optimize machining conditions
- Identify standard tools and coordinates
- Calculate cutter paths and coordinates
- Generate the part program to machine the


ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER  
component

---

A typical dialogue from the machine would be as follows for the operator to identify such things as:



Dept. of ME,




The operator may then examine and prove the program via computer graphics simulation on the console VDU. After this, the program is stored or punched on tape. Although there is some sacrifice in machine utilization, actual programming time is minimal and much tedious production engineering work is eliminated.

2) **Direct Numerical Control:** The process of transferring part programs into memory of a CNC machine tool from a host computer is called Direct Numerical Control or DNC

#### D) PROVING PART PROGRAMS

It is safe practice to check the programmed path for any interference between the tool and the work before using the part program for production. The proving part program is done by:



- Visual inspection
- Single step

## ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

execution

- Dry run
  - Graphical simulation.
- 

**Visual Inspection:** It represents the method of checking visually the program present in the memory of the CNC machine. In this, actual program is run and the programmed movements in all axes are to be checked along with ensuring the tool offset and cutter compensation feature. This method represents the least form of verification and should not be relied up on entirely.

---

Dept. of ME,

**Single Step Execution:** Before auto-running the part program it should be executed in a step mode i.e. block by block. During this execution, spindle speed and feed rate override facilities are to be used so that axes movement can be easily monitored. This operation may be carried out with or without mounting the component on the machine.

**Dry run:** A dry run consists of running the part program in auto-mode. During this, the component is not installed on the machine table and the cutting is done in air. The purpose of this run is to verify the programmed path of the tool under continuous operation and to check whether adequate clearance exist between the clamping arrangement and other projections within the set up. Feed rate override facilities are used to slow down the speed of execution of the program.

**Graphical simulation:** A graphical simulation package emulates the machine tool and, using computer graphics, plots out the machine movements on a VDU screen. Machine movement often takes the form a cutting tool shape moving around the screen according to the programmed movements. When the tool shape passes over a shaded representation of the component, it erases that part of the component. The resulting shape, left after the execution represents the shape of the finished component. Any gross deviations from the intended tool path can be observed and any potential interference can be highlighted.

---

# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

Dept. of ME,

## **PART PROGRAMMING GEOMETRY FOR TURNING**

### **A. COORDINATE SYSTEM FOR A CNC LATHE.**

Machining of a work piece by an NC program requires a coordinate system to be applied to the machine tool. As all machine tools have more than one slide, it is important that each slide is identified individually. There are two planes in which movements can take place

∑ Longitudinal.

∑ Transverse.

Each plane is assigned a letter and is referred to as an axis,

∑ Axis X



Dept. of ME,

$\Sigma$  Axis Z

The two axis are identified by upper case X, Z and the direction of movement along each axis (+) or (-). The Z axis is always parallel to the main spindle of the machine. The X axis is always parallel to the work holding surface, and always at right angles to the Z axis. The coordinate system for turning operations is shown in figure below




Fig 1: COORDINATE SYSTEM FOR TURNING OPERATIONS


## B. ZERO POINTS AND REFERENCE POINTS

All CNC machine tool traverses are controlled by coordinating systems. Their accurate position within the machine tool is established by “ZERO POINTS”.

**MACHINE ZERO POINT (M):** is specified by the manufacturer of the machine. This is the zero point for the coordinate systems and reference points in the machine. On turning lathes, the machine zero point is generally at the center of the spindle nose face. The main spindle axis (center line) represents the Z axis; the face determines the X axis. The directions of the positive X and Z axes point toward the working area as shown in figure below:

# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

Dept. of ME,



**WORKPIECE ZERO POINT (W):** This point determines the workpiece coordinate system in relation to the machine zero point. The workpiece zero point is chosen by the programmer and input into the CNC system when setting up the machine. The position of the workpiece zero point can be freely chosen by the programmer within the workpiece envelope of the machine. It is however advisable to place the workpiece zero point in such a manner that the dimensions in the workpiece drawing can be conveniently converted into coordinate values and orientation when clamping / chucking, setting up and checking, the traverse measuring system can be effected easily.

For turned parts, the work piece zero point should be placed along the spindle axis (center line), in line with the right hand or left hand end face of the finished contour as shown in figure. Occasionally the work piece zero point is also called the “program zero point.”

**REFERNCE POINT (R):** This point serves for calibrating and for controlling the measuring system of the slides and tool traverses. The position of the reference point as shown in figure below is accurately predetermined in every traverse axis by the trip dogs and

**ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER**  
limit switches. Therefore, the reference point coordinates always have the same , precisely  
known numerical value in relation to the machine zero point. After initiating the control  
system, the reference point must always be approached from all axes to calibrate the traverse

---

Dept. of ME,



## ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

|            |  |
|------------|--|
| <b>G02</b> | Circular Interpolation (CW)                        |
| <b>G03</b> | Circular Interpolation (CCW)                       |
| <b>G04</b> | Dwell  |
| <b>G20</b> | Inch Data Input                                    |
| <b>G21</b> | Metric Data Input                                  |
| <b>G28</b> | Reference point return                             |
| <b>G40</b> | Tool nose radius compensation cancel               |
| <b>G41</b> | Tool nose radius compensation left                 |
| <b>G42</b> | Tool nose radius compensation right                |
| <b>G50</b> | Work coordinate change/ Max. Spindle speed setting |
| <b>G70</b> | Finishing cycle                                    |
| <b>G71</b> | Multiple Turning Cycle in turning                  |
| <b>G72</b> | Stock removal in facing                            |
| <b>G73</b> | Pattern repeating                                  |
| <b>G74</b> | Peck drilling in Z axis                            |

---

|  |  |
|--|--|
|  |  |
|  |  |
|  |  |
|  |  |

- G75** Grooving in X axis
- G76** Thread cutting cycle
- G90** Cutting cycle A (Turning)
- G94** Cutting cycle B (Facing)
- G96** Constant surface speed control
- G97** Constant surface speed control cancel
- G98** Feed per minute
- G99** Feed per revolution



ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER  
MISCELLANEOUS FUNCTION (M Codes)

M Codes are instructions describing machine functions such as calling the tool, spindle rotation, coolant on, door close/open etc.

|  |  | <b>M CODES</b>                     |
|--|--|------------------------------------|
|  |  | <b>M00</b> Program Stop            |
|  |  | <b>M02</b> Optional Stop           |
|  |  | <b>M03</b> Spindle<br>Forward (CW) |

---

---

Dept. of ME,



# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

**M30** Program End

**M38** Door Open

**M39** Door Close

**M98** Subprogram Call

**M99** Subprogram Exit

## **COMPUTERISED NUMERICAL CONTROL MILLING**

### **PART PROGRAMMING FUNDAMENTALS**

#### **1. PART PROGRAMMING GEOMETRY**

##### **COORDINATE SYSTEM FOR A CNC MILL**

Machining of a work piece by an NC program requires a coordinate system to be applied to the machine tool. As all machine tools have more than one slide, it is important that each slide is identified individually. There are three planes in which movement can take place.

ÿ Longitudinal

---

Dept. of ME,

• Vertical

• Transverse


Each plane is assigned a letter and is referred to as an axis, i.e,

• Axis X

• Axis Y

• Axis Z

The three axes are identified by upper case X, Y and Z and the direction of movement along each axis is specified as either '+' or '-'. The Z axis is always parallel to the main spindle of the machine. The X axis is always parallel to the work holding surface, and always at right angles to the Z axis. The Y axis is at right angles to both Z and X axis. Figure shows the coordinate system for milling.



## **B. ZERO POINTS AND REFERENCE POINTS**

**MACHINE ZERO POINT (M):** This is specified by the manufacturer of the machine. This is the zero point for the coordinate systems and reference points in the machine. The machine zero point can be the center of the table or a point along the edge of the traverse range as shown in figure the position of the machine zero point generally varies from

**ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER**  
manufacture. The precise position of the machine zero point as well as the axis direction must therefore be taken from the operating instructions provided for each individual machine.

---

Dept. of ME,

**REFERENCE POINT (R):** this point serves for calibrating and for controlling the measuring system of the slides as tool traverses. The position of the reference point is accurately predetermined in every traverse axis by the trip dogs and limit switches. Therefore, the reference point coordinates always have the same, precisely known numerical value in relation to the machine zero point. After initiating the control system, the reference point must always be approached from all axes to calibrate the traverse measuring system. If current slide and tool position data should be lost in the control systems, for example, through an electrical failure, the machine must again be positioned to the reference point to re-establish the proper positioning values.

**WORKPIECE ZERO POINT (W):** This point determines the work piece coordinate system in relation to the machine zero point. The work piece zero point is chosen by the programmer and input into the CNC system when setting up the machine. The position of the work piece zero point can be freely chosen by the programmer within the work piece envelope of the machine. It is however, advisable to place the work piece zero point in such a manner that the dimensions in the work piece drawing can be conveniently converted into coordinate values and orientation when clamping/ chucking, setting up and checking the traverse measuring system can be affected easily. For milled parts, it is generally advisable to use an extreme corner point as the “work piece zero point”. Occasionally, the work piece zero point is called the “program zero point”


---

# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

Dept. of ME,

**NC- RELATED DIMENSIONING**

Dimensional information in a work piece drawing can be stated in two ways:



1. **Absolute Dimension System:** Data in absolute dimension system always refer to a fixed reference point in the drawing as shown in figure A above. This point has the function of a coordinate zero point as in figure B. The dimension lines run parallel to the coordinate axes and always start at the reference point. Absolute dimensions are also called as “Reference dimensions”.

2. **Incremental Dimension System:** When using incremental dimension system, every measurement refers to a previously dimensioned position as shown in figure A below. Incremental dimensions are distance between adjacent points. These distances are converted



**ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER**  
into incremental coordinates by accepting the last dimension point as the coordinate origin for the new point. This may be compared to a small coordinate system, i.e. shifted consequently from point to point as shown in figure B. Incremental dimensions are also frequently called "Relative dimensions" or "Chain dimensions".

---

Dept. of ME,

**PREPARATORY FUNCTIONS (G  
CODES)**

---

| <b>G CODES</b> |                                      |
|----------------|--------------------------------------|
| <b>G00</b>     | Positioning (Rapid Transverse)       |
| <b>G01</b>     | Linear Interpolation (Feed)          |
| <b>G02</b>     | Circular Interpolation (CW)          |
| <b>G03</b>     | Circular Interpolation (CCW)         |
| <b>G04</b>     | Dwell                                |
| <b>G20</b>     | Inch Data Input                      |
| <b>G21</b>     | Metric Data Input                    |
| <b>G28</b>     | Reference point return               |
| <b>G40</b>     | Tool nose radius compensation cancel |
| <b>G41</b>     | Tool nose radius compensation left   |
| <b>G42</b>     | Tool nose radius compensation right  |
| <b>G43</b>     | Tool length compensation + direction |
| <b>G44</b>     | Tool length compensation - direction |
| <b>G73</b>     | Peck drilling cycle                  |
| <b>G74</b>     | Counter tapping cycle                |
| <b>G76</b>     | Fine Boring                          |
| <b>G80</b>     | Canned cycle cancel                  |
| <b>G81</b>     | Drilling cycle, spot boring          |
| <b>G82</b>     | Drilling cycle, counter boring       |
| <b>G83</b>     | Peck drilling cycle                  |
| <b>G84</b>     | Tapping cycle                        |
| <b>G85</b>     | Boring cycle                         |
| <b>G86</b>     | Boring cycle                         |
| <b>G87</b>     | Back boring cycle                    |
| <b>G88</b>     | Boring cycle                         |

# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

Dept. of ME,

|  |  |
|--|--|
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |

- G89** | Boring cycle
- G90** | Absolute command
- G91** | Incremental command
  
- G92** | Programming of Absolute zero point.
- G94** | Feed per minute
- G95** | Feed per revolution
- G98** | Return to initial point in canned cycle
- G99** | Return to R point in canned cycle.

**MISCELLANEOUS AND PREPARATORY FUNCTIONS**

M Codes are instructions describing machine functions such as calling the tool, spindle rotation, coolant on, door close/open etc.

|  |  |                |               |
|--|--|----------------|---------------|
|  |  | <b>M CODES</b> |               |
|  |  |                |               |
|  |  | <b>M00</b>     | Program       |
|  |  | stop           |               |
|  |  | <b>M01</b>     | Optional stop |
|  |  |                |               |
|  |  |                |               |
|  |  |                |               |

# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

|            |  |                         |
|------------|--|-------------------------|
| <b>M02</b> |  | Program end             |
| <b>M03</b> |  | Spindle forward         |
| <b>M04</b> |  | Spindle reverse         |
| <b>M05</b> |  | Spindle stop            |
| <b>M06</b> |  | Tool change             |
| <b>M08</b> |  | Coolant on              |
| <b>M09</b> |  | Coolant off             |
| <b>M10</b> |  | Vice open               |
| <b>M11</b> |  | Vice close              |
| <b>M13</b> |  | Coolant, spindle fwd    |
| <b>M14</b> |  | Coolant, spindle rev    |
| <b>M30</b> |  | Program stop and rewind |

---

Dept. of ME,

|  |  |            |                 |
|--|--|------------|-----------------|
|  |  | <b>M70</b> | X mirror On     |
|  |  | <b>M71</b> | Y mirror On     |
|  |  | <b>M80</b> | X mirror off    |
|  |  | <b>M81</b> | Y mirror off    |
|  |  | <b>M98</b> | Subprogram call |
|  |  | <b>M99</b> | Subprogram exit |

## From the drawing to the workpiece

### 1. Reading drawing




### 2. Programming



### 3. Inputting program



### 4. Manufacturing




# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

Dept. of ME,

**CNC TURNING**

1. Write a manual part program for Linear Interpolation for the given part and execute.



Note: All dimensions are in mm only

**CNC Part Program:**

O1011

G21 G98

G28 X0 Z0

M06 T0101

M03 S100

G00 X10 Z1 M08

G00 X7.5

| C.I.T                              |                                  | Department of ME |  |
|------------------------------------|----------------------------------|------------------|--|
| Particulars                        | Max. Marks                       | Marks Obtained   |  |
| Preparation                        | 05                               |                  |  |
| Performance                        | 10                               |                  |  |
| Viva -Voce                         | 05                               |                  |  |
| Result/Output                      | 05                               |                  |  |
| <b>Total</b>                       | <b>25</b>                        |                  |  |
| <b>Student Signature with date</b> | <b>Staff Signature with date</b> |                  |  |
|                                    |                                  |                  |  |



ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

G01 Z-40 F0.2

G00 X10 Z1

G00 X5

G01 Z-20 F0.2

G00 X10 Z1

G28 X0 Z0


M05 M09

M30

---

Dept. of ME,

2. Write a manual part program for Taper turning for the given part and execute.



Note: All dimensions are in mm only

**CNC Part Program:**

O1012

G21 G98

G28 X0 Z0

M06 T0101

M03 S100

G00 X15 Z1 M08

G00 X10

G01 Z-40 F0.2


G00 X15 Z1

G00 X5

G01 Z-20 F0.2

G00 X15 Z1

G00 X10 Z-40

|  C.I.T |                                  | Department of ME |  |
|---|----------------------------------|------------------|--|
| Particulars   | Max. Marks                       | Marks Obtained   |  |
| Preparation   | 05                               |                  |  |
| Performance   | 10                               |                  |  |
| Viva -Voce  | 05                               |                  |  |
| Result/Output   | 05                               |                  |  |
| <b>Total</b>  | <b>25</b>                        |                  |  |
| <b>Student Signature with date</b>  | <b>Staff Signature with date</b> |                  |  |
|   |                                  |                  |  |

ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER  
G01 X15 Z-60 F0.2

G00 X15 Z1

G00 X5 Z-20

G01 X10 Z-25 F0.2

G00 X15 Z1G28 X0 Z0


M05 M09

M30

---

Dept. of ME,

3. Write a manual part program on Chamfering & Step turning for the given part and execute.



Note: All dimensions are in mm only

**CNC Part Program:**

```
O1013
G21 G98
G28 X0 Z0
M06 T0101
M03 S100
```

```
G00 X50 Z1 M08
```

```
G00 X40
G01 Z-230 F0.2
G00 X50 Z1
G00 X25
G01 Z-130 F0.2
G00 X50 Z1
G00 X15
G01 Z-50 F0.2
G00 X50 Z1
G00 X40 Z-135
G01 X35 Z-130 F0.2
G00 X50 Z1
G00 X25 Z-55
G01 X20 Z-50 F0.2
G00 X50 Z1
G00 X15 Z-5
G01 X10 Z0 F0.2
```

| Particulars                 | Department of ME          |                |
|-----------------------------|---------------------------|----------------|
|                             | Max. Marks                | Marks Obtained |
| Preparation                 | 05                        |                |
| Performance                 | 10                        |                |
| Viva -Voce                  | 05                        |                |
| Result/Output               | 05                        |                |
| <b>Total</b>                | <b>25</b>                 |                |
| Student Signature with date | Staff Signature with date |                |
|                             |                           |                |

ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

G00 X50 Z1

G28 X0 Z0


M05 M09

M30

---

Dept. of ME,

4. Write a manual part program on fillet & Step turning for the given part.



Note: All dimensions are in mm only

**CNC Part Program:**

O1014

G21 G98

G28 X0 Z0

M06 T0101

M03 S100

G00 X60 Z1 M08

G00 X50

G01 Z-330 F0.2

G00 X60 Z1

G00 X30

G01 Z-180 F0.2

G00 X60 Z1

G00 X20

G01 Z-80 F0.2

G00 X60 Z1

G00 X50 Z-185

G02 X45 Z-180 R5

G00 X60 Z1

G00 X30 Z-83

G02 X27 Z-80 R3

G00 X60 Z1

G00 X20 Z-2

| Particulars                        | Department of ME                 |                |
|------------------------------------|----------------------------------|----------------|
|                                    | Max. Marks                       | Marks Obtained |
| Preparation                        | 05                               |                |
| Performance                        | 10                               |                |
| Viva -Voce                         | 05                               |                |
| Result/Output                      | 05                               |                |
| <b>Total</b>                       | <b>25</b>                        |                |
| <b>Student Signature with date</b> | <b>Staff Signature with date</b> |                |
|                                    |                                  |                |

ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

G02 X18 Z0 R2

G00 X60 Z1

G28 X0 Z0


M05 M09

M30

---

Dept. of ME,

5. Write a manual part program for the given profile and execute.



Note: All dimensions are in mm only

**CNC Part Program:**

```
O1015
G21 G98
G28 X0 Z0
M06 T0101
M03 S100
G00 X50 Z1 M08
G00 X40
G01 Z-134 F0.2
G00 X50 Z1
G00 X30
G01 Z-98 F0.2
G00 X50 Z1
G00 X15
G01 Z-58 F0.2
G00 X50 Z1
G00 X40 Z-134
G01 X50 Z-154 F0.2
G00 X50 Z1
G00 X30 Z-98
G03 X40 Z-114 R16
```

```
G00 X10
G01 X15 Z-30
F0.2
G00 X50 Z1
G28 X0 Z0
M05 M09
M30
```

| Particulars                        | Department of ME                 |                |
|------------------------------------|----------------------------------|----------------|
|                                    | Max. Marks                       | Marks Obtained |
| Preparation                        | 05                               |                |
| Performance                        | 10                               |                |
| Viva -Voce                         | 05                               |                |
| Result/Output                      | 05                               |                |
| <b>Total</b>                       | <b>25</b>                        |                |
| <b>Student Signature with date</b> | <b>Staff Signature with date</b> |                |
|                                    |                                  |                |



ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER


G00 X50 Z1

G00 X15 Z-58

G02 X30 Z-78 R20

G00 X50 Z1

6. Write a manual part program for the given profile and execute.



Note: All dimensions are in mm only

**CNC Part Program:**

O1016

G21 G98  
G28 X0 Z0  
M06 T0101  
M03 S100

G00 X25 Z1 M08  
G00 X15  
G01 Z-30 F0.2  
G00 X25 Z1

G00 X25 Z-60  
G01 X15 Z-95 F0.2  
G00 X25 Z-95  
G00 X25 Z1  
G00 X25 Z-95  
G00 X15 Z-95  
G01 X15 Z-125 F0.2  
G00 X25 Z-125  
G00 X25 Z1  
G00 X25 Z-125  
G00 X15 Z-125  
G02 X25 Z-135 R10  
G00 X25 Z-135  
G00 X25 Z1

G02 X0 Z0 R10

G00 X25 Z1  
G28 X0 Z0  
M05 M09  
M30

| Particulars                        | Department of ME                 |                |
|------------------------------------|----------------------------------|----------------|
|                                    | Max. Marks                       | Marks Obtained |
| Preparation                        | 05                               |                |
| Performance                        | 10                               |                |
| Viva -Voce                         | 05                               |                |
| Result/Output                      | 05                               |                |
| <b>Total</b>                       | <b>25</b>                        |                |
| <b>Student Signature with date</b> | <b>Staff Signature with date</b> |                |
|                                    |                                  |                |

ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

G00 X15 Z-30

G02 X25 Z-40 R10


G00 X25 Z1

G00 X15 Z-10

---

Dept. of ME,

7. Write a manual part program for the given profile and execute.



Note: All dimensions are in mm only

**CNC Part Program:**

```
O1017
G28 X0 Z0
M06 T0101
M03 S100
G00 X25 Z1 M08

G00 X20

G01 Z-135 F0.2
G00 X25 Z1
G00 X15
G01 Z-95 F0.2
G00 X25 Z1
G00 X10
G01 Z-55 F0.2
G00 X25 Z1
G00 X10 Z-20
G01 X0 Z0 F0.2
G00 X25 Z1
G28 X0 Z0
M05 M09
M30
```


| C.I.T                              |                                  | Department of ME |  |
|------------------------------------|----------------------------------|------------------|--|
| Particulars                        | Max. Marks                       | Marks Obtained   |  |
| Preparation                        | 05                               |                  |  |
| Performance                        | 10                               |                  |  |
| Viva -Voce                         | 05                               |                  |  |
| Result/Output                      | 05                               |                  |  |
| <b>Total</b>                       | <b>25</b>                        |                  |  |
| <b>Student Signature with date</b> | <b>Staff Signature with date</b> |                  |  |
|                                    |                                  |                  |  |

# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER


Dept. of ME,

**PRACTICE PROGRAMS [CNC TURNING]**


8.



9.



10.




Note: All dimensions are in mm only

---

Dept. of ME,

**CNC MILLING**

1) Write a manual part program for Slotting operation for the component as shown in drawing and execute.



Material – Mild Steel,

Operation - Slotting

Billet size – 100 x 100 x 15mm

Tool – Radiused end mill  $\Phi$  10 mm

Note: All dimensions are in mm only

**CNC Part Program:**

O1021  
G21 G98  
G28 X0 Y0 Z0

| Particulars | Department of ME |                |
|-------------|------------------|----------------|
|             | Max. Marks       | Marks Obtained |
| Preparation | 05               |                |
| Performance | 10               |                |



# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

M06 T0101

M03 S100

G00 X25 Y75 Z5 M08

G01 Z-5 F0.2

Y25

X75

Y75

G00 Z5

G28 X0 Y0 Z10


M05 M09

M30

---

Dept. of ME,

2) Write a manual part program for Drilling operation for the component as shown in drawing.



Note: All dimensions are in mm only

Material – Mild Steel,

Operation - Drilling

Billet size – 60 x 60 x 30mm

Tool – Slot drill  $\Phi$  10 mm

**CNC Part Program:**

```
O1022
G21 G98
G28 X0 Y0 Z0
M06 T0101
M03 S100
G00 X15 Y15 Z5 M08
G01 Z-10 F0.2
G00 Z5
G00 X15 Y45
G01 Z-10 F0.2
G00 Z5
G00 X45 Y45
G01 Z-10 F0.2
G00 Z5
G00 X45 Y15
G01 Z-10 F0.2
G00 Z5
```

| Particulars                        | Department of ME                 |                |
|------------------------------------|----------------------------------|----------------|
|                                    | Max. Marks                       | Marks Obtained |
| Preparation                        | 05                               |                |
| Performance                        | 10                               |                |
| Viva -Voce                         | 05                               |                |
| Result/Output                      | 05                               |                |
| <b>Total</b>                       | <b>25</b>                        |                |
| <b>Student Signature with date</b> | <b>Staff Signature with date</b> |                |
|                                    |                                  |                |

ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

G28 X0 Y0 Z0


M05 M09

M30

---

Dept. of ME,

3) Write a manual part program for the profile as shown in the drawing and execute.



Note: All dimensions are in mm only

Material – Mild Steel,

Operation – Milling

Billet size – 120 x 80 x 10mm

Tool – Radiused end mill  $\Phi$  5mm

**CNC Part Program:**

```
O1023
G21 G98
G28 X0 Y0 Z0

M06 T0101
M03 S100
G00 X0 Y10 Z5 M08
G01 Z-10 F60
X10 Y0
X80
X90 Y10
G02 X120 Y40 Z-10 R30
G01 X120 Y80 Z-10 F60
X60 Y80
X60 Y70
X50 Y70
G02 X30 Y60 Z-10 R20
G01 X0 Y60 Z-10 F60
```

| C.I.T                              |                                  | Department of ME |  |
|------------------------------------|----------------------------------|------------------|--|
| Particulars                        | Max. Marks                       | Marks Obtained   |  |
| Preparation                        | 05                               |                  |  |
| Performance                        | 10                               |                  |  |
| Viva -Voce                         | 05                               |                  |  |
| Result/Output                      | 05                               |                  |  |
| <b>Total</b>                       | <b>25</b>                        |                  |  |
| <b>Student Signature with date</b> | <b>Staff Signature with date</b> |                  |  |
|                                    |                                  |                  |  |

ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

X0 Y10

G28 X0 Y0 Z0


M05 M09

M30

---

Dept. of ME,

4) Write a manual part program for the profile as shown in the drawing and execute.



Note: All dimensions are in mm only

Material – Mild Steel,

Operation – Milling

Billet size – 100 x 60 x 15mm

Tool – Radiused end mill  $\Phi$  10mm

**CNC Part Program:**

O1024

G21 G98  
G28 X0 Y0 Z0  
G41 M06 T0101  
M03 S600  
G00 X0Y0 Z5 M08  
G01 Z-10 F0.2  
G01 X0 Y45  
G01 X15 Y60  
G01 X100  
G01 Y15  
G01 X80  
G01 Y0  
G01 X0  
G0 Z5  
G28 X0 Y0 Z0  
M05M09

| Particulars                        | Department of ME                 |                |
|------------------------------------|----------------------------------|----------------|
|                                    | Max. Marks                       | Marks Obtained |
| Preparation                        | 05                               |                |
| Performance                        | 10                               |                |
| Viva -Voce                         | 05                               |                |
| Result/Output                      | 05                               |                |
| <b>Total</b>                       | <b>25</b>                        |                |
| <b>Student Signature with date</b> | <b>Staff Signature with date</b> |                |
|                                    |                                  |                |


ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

M30

---

Dept. of ME,

5) Write a manual part program for the profile as shown in the drawing and execute.



Note: All dimensions are in mm only

Material – Mild Steel,

Operation – Milling

Billet size – 100 x 60 x 15mm

Tool – Radiused end mill  $\Phi$  10mm

**CNC Part Program:**

O1025

G21 G98

G28 X0 Y0 Z0

G42 M06 T0101


M03 S100

G00 X20 Y20 M08

G01 Z-10 F0.2

G03 X60 Y20 R20

G03 X60 Y60 R20

|  C.I.T |                                      | Department of<br>ME |  |
|---|--------------------------------------|---------------------|--|
| Particulars   | Max.<br>Marks                        | Marks<br>Obtained   |  |
| Preparation   | 05                                   |                     |  |
| Performance   | 10                                   |                     |  |
| Viva -Voce  | 05                                   |                     |  |
| Result/Output   | 05                                   |                     |  |
| <b>Total</b>  | <b>25</b>                            |                     |  |
| <b>Student Signature<br/>with date</b>  | <b>Staff Signature with<br/>date</b> |                     |  |
|   |                                      |                     |  |



ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

G03 X20 Y60 R20

G03 X20 Y20 R20

G00 Z5

G28 X0 Y0 Z0


M05 M09

M30

---

Dept. of ME,

6) Write a manual part program for the profile as shown in the drawing and execute.



Note: All dimensions are in mm only

Material – Mild Steel,

Operation – Slotting

Billet size – 100 x 105 x 15mm

Tool – slot drill  $\Phi$  15mm

**CNC Part Program:**

O1027  
G21 G98  
G28 X0 Y0 Z0  
M06 T0101  
M03 S100  
G00 X-8 Y22.5 M08  
G01 Z-5 F0.2  
G01 X108 F0.2  
G00 Y52.5  
G01 X-8 F0.2  
G00 Y82.5  
G01 X108 F0.2  
G00 Z10

| Particulars                        | Department of ME                 |                |
|------------------------------------|----------------------------------|----------------|
|                                    | Max. Marks                       | Marks Obtained |
| Preparation                        | 05                               |                |
| Performance                        | 10                               |                |
| Viva -Voce                         | 05                               |                |
| Result/Output                      | 05                               |                |
| <b>Total</b>                       | <b>25</b>                        |                |
| <b>Student Signature with date</b> | <b>Staff Signature with date</b> |                |
|                                    |                                  |                |


ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER  
G28 X0 Y0 Z10

M05 M09  
M30

---

Dept. of ME,

7) Write a manual part program for the profile as shown in the drawing and execute.



Material – Mild Steel,

Operation – milling & drilling

Billet size – 120 x 80 x 10mm

Tool – slot drill  $\Phi$  10mm

Note: All dimensions are in mm only

**CNC Part Program:**

O1027

G21 G98

G28 X0 Y0 Z0

M06 T0101

M03 S600

G00 X0 Y10 Z5 M08

G01 Z-10 F60

X10 Y0

X80

X90 Y10

G00 X105 Y70

Z5


G01 Z-10 F60

G00 Z5

G28 X0 Y0 Z0

M05 M09

M30

|  |                         |                   |
|--|-------------------------|-------------------|
|  <b>C.I.T</b> | <b>Department of ME</b> |                   |
|  | <b>Particulars</b>      | <b>Max. Marks</b> |
| Preparation  | 05                      |                   |

# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

G02 X120 Y40 Z-10 R30

G01 X120 Y80 Z-10 F60

X60 Y80

X60 Y70

X50 Y70

G02 X30 Y60 Z-10 R20

G01 X0 Y60 Z-10 F60

X0 Y10

G00 X0 Y0 Z5

G00 X25 Y20 Z5

G01 Z-10 F60

G00 Z5

G00 X65 Y20 Z5

G01 Z-10 F60


G00 Z5

---

Dept. of ME,


**PRACTICE PROGRAMS [CNC MILLING]**

8.



Note: All dimensions are in mm only

9.




# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

Note: All dimensions are in mm only

---

Dept. of ME,

10.



Note: All dimensions are in mm only




# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

Dept. of ME,

**TO GENERATE THE PROGRAM**

**8 steps in CAPSTURN/CAPSMILL NC programming**



**1. Start new program**

Double click on the CAPSTURN icon

Or

Select start- program –CADEM –CAPSTURN

**2. Define work setup**

Setup data is required for machining, and documentation is related to the details of the program. The work setup data is divided into

Setup data 1,

Setup data 2 and

Documentation.

Entering the setup data I mandatory, while documentation is optional.

# ST. WILFRED'S INSTITUTE OF ENGINEERING & TECHNOLOGY, AJMER

Dept. of ME,

### **3. Draw the part**

Draw-use the drawing tools to construct the geometry of the part

Draw-define part – create part shape

### **4. Draw the blank**

Draw –define blank

### **5. Perform machining**

Switch to the machining menu clicking on the machining tab

Select appropriate machining operation and define tool details used for that operation

### **6. Select machine**

Select suitable machine from the available list

### **7. View tool path.**

Switch to tool path mode by clicking on tool path tab

Select tool path-start

### **8. Generate NC program**

Click on NC PROGRAM ON THE menu bar

---